ARM Nauru Research Station Site Visit 0311N Report

Visit Duration: 10 November to 12 November

Denig District, Republic of Nauru

SITE: Nauru

SV 0311 N (H2 Genset Service)

Team Members:

Troy Culgan, Australian BOM

<u>Dates of Visit</u> From November 10 - 14, 2003

Pı		Date	Service	Tasks/Description of Work/Process
riority	System	Completed	Time in	•
ty		(dd/Month)	Hours	For each priority item insert new line(row) for each date/time entry
1	H2GEN			Electrolyser routine maintenance
		12-Nov	15 Hrs	Completed
	110051			
2	H2GEN			Deliver "age blooding" bit and train Observers on its use using new procedure
		10-Nov	19 Hrs transit	Deliver "gas bleeding" kit and train Observers on its use using new procedure. Completed
		10-1107	19 THS transit	Completed
3	H2GEN			
				Walk through balloon launching process with Observers and written procedure.
		12-Nov	1 hr	Completed
4	MPL			Install LASER Diode.
		10-Nov	1.5 Hrs	Laser Diode suppy Ser No 3332 replaced with unit serial No 3689
5	AERI			Repair Unit
<u> </u>	AERI			Repair Offic
		11-Nov	1Hr	Media converter connection faulty (Re-boot Ethernet to Fiber converter in SDS
		111101		Rack). Rex verified remote connectivity. Observers trained for future reference.
				,
6	GENSET			Find a way that we can use gravity feed truck to obtain fuel for our site.
		13-Nov	30 min	Reviewed procedure with observers for transfer of fuel from gravity feed truck
	14/01		00 111111	when it becomes available
7	WSI			Replace corrosion prevention parts in ARC Drive. Replace/clean metal filter inside I-Van and in field unit, change out shutter assembly, and replace
				desiccant cylinder.
				Desiccant and filters replaced during SV0309N(cal). Shutter assembly to be
		12-Nov	10 min	changed out just prior to WSI Calibration - therefore not changed this visit.
				Spares on site:desicant cylinders 3, Corrosion prevention parts: nil
8	AERI			Changeout Computer Filter
\vdash		11-Jan	1 Hr	Filter changed
9	MPL			Sunshade repair check
<u> </u>	IVIFL	10-Nov	30 min	Check on repair and relocated control unit to the rack
		10 140	00 111111	zaran zara zara ana rasasasa aana a ank ta kio kan
10	COM			Power outfitter satphone through 24 volt batt pack in E-Van using 24-12 volt
				DC/DC converter.
		12-Nov	2 Hr	Completed
	OFNOFT			Occurs Described filters because the first filter of D. H. C. C. C. C.
11	GENSET			Oversee Racor fuel filter changeout in the Fuel Transfer Dolly for tank to tank
		12-Nov	15 min	transfer Viewed observers changeout Racor fuel filter in Fuel Transfer Dolly
		12-INUV	13 111111	VICWED ODSERVERS CHANGEOUT NACOF IDEL IIITE DEL TRANSIEL DOILY
12	IRT			Change out gold mirror
		12-Nov	15 min	Changed out gold mirror completed (11 Nov 20:00 UTC)

P		Date	Service Time in Hours	Tasks/Description of Work/Process
rio	System	Completed (dd/Month)		For each priority item insert new line(row) for each date/time entry
iority				
13	Other			Remove all equipment from Menen Room 201 and close out with Andrew
				Kaierua and Hotel Manager.
		13-Nov	1hr	Room cleared and ready for close out
14	Other			Verify diesel shed complete and drums in containment holders.
		11-Nov	10 Min	Shed appears complete,photo sent to Monty Apple
15	Other			Install external mouse AWS Metconsole
		12-Nov	15 min	Completed
15	DAQ-S			Verify skyrad logger serial and WD number inside can
10	DAQ-3	13-Nov	30 min	Verified by Visual sighting Loggger Ser#030 WD25946 Zeno Ser# 098
16	Van	13-1404	30 111111	3-phase monitors: Replace on U-Van/ install on D-Van.
10	Vali	12-Nov	30 min	Replaced U-Van 3-phase monitor, D-Van already has one
		12-1107	30 111111	replaced 6 van 6 phase monitor, 5 van alleddy has one
17	TSI			Perform and instruct observers on the new monthly re-boot procedure. Also
				review cleaning procedure with wax.
		12-Nov	15 min	Completed instruction with Nic, Franklin and Robroy
18	IRT			Compare GNDRAD IRT readings w/ blackbody.
		13-Nov	1hr	Comparision complete report to be sent to Bill Porch
	Future			WSI Volatile Corrosion Inhibitor Cylinder (2 ea) and WSI Volatile Corrosion
	Needs			Inhibitor Rectangle (2 ea). Change out WSI Camera Shutter just before WSI
				Calibration.
	Shipping			Ship old MPL Shutter Assembly components (except for tube), back to SGP
	Shipping			(via Interconex).
	MMCR	13-Nov	2hr	Reseated control boards for TWTA as it failed to power up